PC-900 Printer
Installation Instruction

PC-900

First step: take out the battery

-

Bottom of the monitor

Second step: take out the screws

The screws are to fix the front panel
**Screw: ST3×12**

Third step: open the front panel

# Fourth step: Separate front and rear parts of the monitor

Fifth step: take out screws from the main frame

-

The screws are to fix the main frame

Sixth step: take out the main frame (with module)

-

Power cable (connected to the printer)

**Replace the printer cover with the printer**

Printer module

Signal cable port

Power cable port

Main board

-

Main Signal cable port (connected to interface board)

Signal cable port (connected to printer)

Finished

- Kindly note: pls turn off the monitor and take out the battery before dismantle the monitor.